

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
04/22/2014

Document Number:
674600260

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>216087</u>	<u>333792</u>	<u>Maclaren, Joe</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>66575</u>
Name of Operator:	<u>PABLO OPERATING COMPANY</u>
Address:	<u>777 MAIN ST STE 3250</u>
City:	<u>FT WORTH TX 76102</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Neely, Roger		rtneely@anklaw.com	SW Inspections
Patton, Paula	817-332-1328	ppatton@sproles.com	SW Inspections
Heller, Bruce	970-247-4036	bruceheller@durangolive.net	Heller Corp. Contract Pumper

Compliance Summary:

QtrQtr:	<u>SENW</u>	Sec:	<u>27</u>	Twp:	<u>33N</u>	Range:	<u>8W</u>
---------	-------------	------	-----------	------	------------	--------	-----------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/06/2008	200196266	PR	PR	SATISFACTOR Y			No

Inspector Comment:

There is an unlabeled and unbermed blowdown tank connected to the wellhead on the Jaques #5F via a flexible hose. This tank will need to be removed as soon as well maintenance operations have been completed; or have proper labeling (per 210.d.) and adequate berming installed (per 604-2.G.) per facility installation requirements. Temporary berming can be utilized, but must meet capacity requirements. There is one exception to this rule; tanks holding produced water that contains less than 3500 mg/l total dissolved solids becomes exempt from this berming requirement.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214007	WELL	PR	12/10/1959	GW	067-05294	JACQUES 1	PR <input checked="" type="checkbox"/>
216087	WELL	PR	11/05/1991	GW	067-07693	JAQUES 5-F	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	ACTION REQUIRED	Temporary blowdown tank has no labeling.	Install sign to comply with rule 210.	05/21/2014

Emergency Contact Number: (S/U/V) SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	Drilling cable on Jaques #1 location. Unlabeled barrel, etc on interim disturbance on SE corner of Jaques #5F location. Picture uploaded.	Remove trash from location per rule 603.f.	05/21/2014
STORAGE OF SUPL	ACTION REQUIRED	Wood blocks, sucker rods, uncovered chemical containment pan, misc valves, hardware etc. Picture uploaded.	Remove unused supplies and equipment from location.	05/21/2014

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Guard Fencing		
PIT	SATISFACTORY	Post and wire		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Flow Line	2	SATISFACTORY			
Vertical Heated Separator	1	SATISFACTORY			
Ancillary equipment	3	SATISFACTORY	Gas line risers with valves		
Bird Protectors	1	ACTION REQUIRED	No visable bird protector in exhaust stack on vertical heated separator or produced water tank on #5F location.	Confirm existence of or install bird protectors per rule 605b.7.	05/09/2014
Ancillary equipment	2	SATISFACTORY	Flowing wellhead		

Inspector Name: Maclaren, Joe

Horizontal Heated Separator	1	SATISFACTORY		
Gas Meter Run	2	SATISFACTORY		

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST	37.076490,-107.707970
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLs	BV FIBERGLASS	37.076960,-107.707660
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment	Berミング will need maintenance to prevent storwater run-on into open top tank.			

The subreport 'rptInsp8' could not be found at the

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 216087

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 214007 Type: WELL API Number: 067-05294 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 216087 Type: WELL API Number: 067-07693 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

The subreport 'rptInsp12' could not be found at the

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
- Waste Material Onsite? In CM _____
CA _____ CA Date _____
- Unused or unneeded equipment onsite? In CM _____
CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: There may be subsidence taking place over the drilling pit that appears to be located off of the south end of the Jaques #5F location. Picture uploaded.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Inspector Name: Maclaren, Joe

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			Culvert between well pads crushed and plugged
				CM	Fail	Unused chemical pan with no cover
Gravel	Pass	Gravel	Pass			
Berms	Fail					No berming around blowdown tank
Compaction	Pass	Compaction	Pass			

S/U/V: _____ Corrective Date: 05/21/2014

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674600270	Chemical spill prevention pan with no cover	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327015
674600271	Inadequate berming around BV	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327016
674600272	No berming around steel ast blowdown tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327017
674600273	Filled in culvert	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327018
674600274	Trash on SE corner interim disturbance area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327019
674600275	Possible subsidence over drilling pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3327020