

Reference Area Photographs

Inspection Conducted on April 23, 2014

**Linn Energy LLC
Chevron 13-16D
Garden Gulch Rd
Location ID #335616**

Linn Energy LLC - Chevron 13-16D



Aerial Photo from COGIS Map – Year 2011
Pit 280 x 60 feet approximately.



From the Southeast to the Northwest. Two large stockpiles that were not present in 2011 occupy now half of the pad area, on the downgradient side (northwest).

Linn Energy LLC - Chevron 13-16D



Large stockpile, about 15 feet high and 45 feet long.



Pieces of liner mixed with the stockpiled material.



Pieces of liner.



Junk in the stockpile



Stockpile at the edge of the slope.



More stockpiled material.

Linn Energy LLC - Chevron 13-16D



Natural drainage at the bottom. Site is located in the Roan Rim Area .



Stormwater Management. Reclaimed area.
Pieces of liner incorporated into the soil.

Linn Energy LLC - Chevron 13-16D



Pieces of liner blown by the wind, impacting (what should be) undisturbed areas.



Pieces of liner and garbage incorporated into the soil (interim reclamation) and outside of the pad.

Linn Energy LLC - Chevron 13-16D



Interim Reclamation. Reclaimed area with pieces of liner incorporated into the soil.



Reclaimed area: Close-up of soil with pieces of liner half-buried in the ground.



Piece of liner pulled from the ground.



This is apparently sand blasting sand used for maintenance of nearby tank .