



File Name: 20140603-1_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Well Sign



File Name: 20140603-2_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Well sign, junk and debris near entrance of the pad.



File Name: 20140603-3_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Unmarked guy line anchor.



File Name: 20140603-4_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: northeast

Description: View of revegetation in progress on the pad. No surface indication of the plugged well.



File Name: 20140603-5_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: north

Description: View of revegetation in progress on the pad. No surface indication of the plugged well.



File Name: 20140603-6_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: east

Description: View of revegetation in progress on access road.



File Name: 20140603-7_JW_dda

FEDERAL LAND BANK #15-4C, API No. 05-081-06700

Date: 06-03-2014

Photographer: David Andrews

Facing: northeast

Description: View of revegetation in progress on access road.