



File Name: 20140603-1\_HRM\_dda

**F L B UT/BIGHOLE DEEP #23-2, API No. 05-081-06413**

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Damaged piece of 20" surface casing



File Name: 20140603-2\_HRM\_dda

**F L B UT/BIGHOLE DEEP #23-2, API No. 05-081-06413**

Date: 06-03-2014

Photographer: David Andrews

Facing: southwest

Description: Damaged piece of 20" surface casing (foreground to the left), 30" conductor pipe, and 13-5/8" intermediate casing. Damaged wellhead and new BOPE in the background.





File Name: 20140603-3\_HRM\_dda

**F L B UT/BIGHOLE DEEP #23-2, API No. 05-081-06413**

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Attaching overshot patch and riser to 3-1/2" tubing.



File Name: 20140603-4\_HRM\_dda

**F L B UT/BIGHOLE DEEP #23-2, API No. 05-081-06413**

Date: 06-03-2014

Photographer: David Andrews

Facing: west

Description: Slipping 9-5/8" casing over 3-1/2" tubing with crane.



File Name: 20140603-5\_HRM\_dda

**F L B UT/BIGHOLE DEEP #23-2, API No. 05-081-06413**

Date: 06-03-2014

Photographer: David Andrews

Facing: northwest

Description: Slipping 30" conductor pipe over 9-5/8" casing with crane.