

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/14/2014

Document Number:
667200156

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>218852</u>	<u>387770</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>41365</u>
Name of Operator:	<u>HRBEK* RANDALL L</u>
Address:	<u>P O BOX 159</u>
City:	<u>MERINO</u> State: <u>CO</u> Zip: <u>80741</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
AXELSON, JOHN		john.axelson@state.co.us	
BURN, DIANA		diana.burn@state.co.us	
NOTO, JOHN		john.noto@state.co.us	
Hrbek, Randall		kebrh@kci.net	
WEEMS, MARK		mark.weems@state.co.us	
ASH, MARGARET		margaret.ash@state.co.us	
SUTPHIN, DIRK		dirk.sutphin@state.co.us	
Kirst, Don		ccso299@olyphen.com	Landowner

Compliance Summary:

QtrQtr:	<u>SESW</u>	Sec:	<u>26</u>	Twp:	<u>8N</u>	Range:	<u>54W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/11/2014	667200150	PA	EI	VIOLATION			Yes
04/28/1995	500152700	SR	PA		P		
04/25/1995	500152699	SR	PA		P	Pass	No

Inspector Comment:

Re-inspection performed by COGCC Inspector Schure on 6/14/2014 of spill identified as originating from 05-075-05619 (Luther I), Operator Randall Hrbek. Schure scheduled an on-sight meeting with the tenant farmer who has been serving the absentee landowner Mr. Don Kirst (360) 808-3397 for the past 40yrs. in the attempt to verify the identification of the well causing the spill/release. The result of the re-inspection indicates the previous inspection Doc.# 667200150 identifying the source of the spill as the (Luther 1) 05-075-05619 was "misidentified" and is corrected by this Inspection Report as the (Luther 2) 05-075-56169 Operator: New Drilling Co. #62500. No Operator contact information is available on the COGCC database.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
116391	PIT		09/23/1999		-	LUTHER	<input type="checkbox"/>
218852	WELL	PA	11/17/1994	OW	075-05619	LUTHER 1	PA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: SCHURE, KYM

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 218852

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 218852 Type: WELL API Number: 075-05619 Status: PA Insp. Status: PA

Complaint

Comment: COGCC Inspector Schure performed a re-inspection of this site for confirmation of identification of well source of spill. Inspection Doc#667200150 is corrected by Doc# 667200156 verifying the source of the spill previously mis-identified as the (Luther 1) 05-075-05619 is re-identified as the (Luther 2) 05-075-56169 Operator # 62500 "New Drilling Co." No Operator contact information available on the COGCC database for New Drilling Co.

Environmental

Spills/Releases:

Type of Spill: OIL Description: _____ Estimated Spill Volume: _____

Comment: _____

This inspection is a correction from Doc. # 667200150. Well surface pipe (surface conduit) exposed approximately (2)' below surface grade. Oil/Crude was ejected from well in a South by South-east direction approximately 300' in a linear path from the well. Source of spill is identified/corrected originating from API# 05-075-56169.

Corrective Action: **NO CORRECTIVE ACTION REQUIRED ON THIS API#05-075-05619** Date: **06/14/2014**

Reportable: YES GPS: Lat 40.625890 Long -103.388860

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____

Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: SCHURE, KYM

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						

S/A/V: SATISFACTOR Corrective Date: _____
Y

Comment: Site is located in Dryland/Cropland. No surface erosion from stormwater runoff was observed.

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667200156	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3365427