

Jolley –KP 11-16

Inspection # 675200103


Debris near  
ECU.



Rilling and  
erosion on cut  
slope.



Staining  
around  
wellheads



Cuttings pile

