

API: 057- 06094

06/18/2014

Site Inspection pictures (total)



Leak at well head.



Leak from barrel behind well head.



Erosion from cut on location.



Sediment run-off, by pit and fencing down (1).



Sediment run-off, by pit and fencing down (2).



Debris on site.