

API: 057- 06065

06/18/2014

Site Inspection pictures (4 total)



Oil run-off from spill still present.



Cuttings/ dewatering mud pile with oily residue found on-site.



Location fencing removed.



Debris and perimeter erosion.