

HMU – 68S92W 6NWSE

Inspection DOC# 675200167

Erosion on cut slope.



Tubing sticking out of ground.



Tubing sticking out of
ground.

