

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
07/01/2014

Document Number:  
674600590

Overall Inspection:

**ACTION REQUIRED**

**FIELD INSPECTION FORM**

|                     |               |               |                      |                    |                          |
|---------------------|---------------|---------------|----------------------|--------------------|--------------------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:      | On-Site Inspection | <input type="checkbox"/> |
|                     | <u>215289</u> | <u>325718</u> | <u>Maclaren, Joe</u> | 2A Doc Num:        |                          |

**Operator Information:**

|                       |   |
|-----------------------|---|
| OGCC Operator Number: | <u>16695</u>                                      |
| Name of Operator:     | <u>CHEVRON MIDCONTINENT LP</u>                    |
| Address:              | <u>1400 SMITH STREET - ROOM 44195</u>             |
| City:                 | <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77002</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email                  | Comment |
|--------------|-------|------------------------|---------|
| Pohl, April  |       | april.pohl@chevron.com |         |

**Compliance Summary:**

QtrQtr: NWNE Sec: 35 Twp: 35N Range: 9W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/28/2005 | 200066832 | ID         | SI          | SATISFACTOR Y                 |          | Pass           | No              |
| 03/27/2001 | 200016331 | ID         | SI          | SATISFACTOR Y                 |          | Pass           | No              |
| 09/04/1997 | 500148769 | ID         | SI          |                               |          | Pass           | No              |
| 12/03/1996 | 500148768 | ID         | SI          |                               |          | Fail           | Yes             |
| 11/13/1995 | 500148767 | ID         | SI          |                               |          | Pass           | No              |

**Inspector Comment:**

Overall status of this inspection is Action Required based on weeds around well head/ pad (noxious) and the need to mark rig anchors that are being overgrown/ buried by soil and vegetation. A succesful MIT was completed on this well on 3/5/2013 - Doc #1772601.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|-------------------------------------|
| 215289      | WELL | SI     | 08/17/1992  | OBW        | 067-06894 | DAY-V RANCH 1-35 | SI          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

Inspector Name: Maclaren, Joe

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |  |  |            |
|---------------------------|------------------------------|--|--|------------|
| Type                      | Satisfactory/Action Required | Comment  | Corrective Action  | CA Date    |
| WEEDS                     | <b>ACTION REQUIRED</b>       | Thistles (noxious weeds) around wellhead and across wellpad.                                   | Remove existing weeds from around wellhead and well pad and control future growth. | 08/18/2014 |
| OTHER                     |                              | Un-used concrete foundation structures and flowline pipe/ materials scattered around well pad. |  |            |

| <b>Spills:</b> |      |        |                   |         |
|----------------|------|--------|-------------------|---------|
| Type           | Area | Volume | Corrective action | CA Date |

Multiple Spills and Releases?

| <b>Equipment:</b>  |   |                              |  |                                  |            |
|--------------------|---|------------------------------|--|----------------------------------|------------|
| Type               | # | Satisfactory/Action Required | Comment                                      | Corrective Action                | CA Date    |
| Other              | 1 | SATISFACTORY                 | Shut in wellhead                             |                                  |            |
| Flow Line          | 1 | SATISFACTORY                 | Partially exposed on north side of well pad. |                                  |            |
| Deadman # & Marked | 4 | <b>ACTION REQUIRED</b>       | Rig anchors are not marked                   | Mark all rig anchors on well pad | 08/18/2014 |

| <b>Venting:</b> |         |
|-----------------|---------|
| Yes/No          | Comment |
| NO              |         |

| <b>Flaring:</b> |                              |         |                   |         |
|-----------------|------------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                 |                              |         |                   |         |

**Predrill**

Location ID: 215289

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 215289 Type: WELL API Number: 067-06894 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

S/AV: SATISFACTORY CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed?   In   CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite?   Pass   CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite?   Pass   CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?   Pass   CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked?   Fail   CM   Anchors not marked  

CA   Mark all rig anchors   CA Date   08/18/2014  

1003b. Area no longer in use?   Pass   Production areas stabilized ?   Pass  

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed?   Pass   Subsidence over on drill pit?   Pass  

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?   Pass  

Production areas have been stabilized?   Pass   Segregated soils have been replaced?   Pass  

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Inspector Name: Maclaren, Joe

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? I

Comment: Thistles surrounding wellhead and scattered across well pad that are in need of removal and future control.

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                         | URL   |
|--------------|-------------------------------------|---|
| 674600608    | Thistles around wellhead            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381176</a> |
| 674600609    | Unmarked Rig anchor                 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381177">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381177</a> |
| 674600610    | Un-used concrete structures         | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381178">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381178</a> |
| 674600611    | Partially buried flowline and valve | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381179">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3381179</a> |