

# Savage RWF 22-25

Inspection DOC# 675200190

Sediment has gone  
around straw bales on  
East end of location.



Erosion and rilling on  
cut slope.



No visible storm water  
BMPs on access road.

