

## Savage RWF 23-25

Inspection DOC# 675200191

Sediment has gone into  
vegetation off of main  
road.



Erosion from road at  
culvert. Culvert outlet  
not armored.





Erosion on road, no ditch  
in place.



Staining on location



Stored equipment



Cuttings stacked on location.

