

DOWNING-66S94W - #335511

07/11/2014 Inspection pictures (4 total).



Southern cut of pad being compacted and re-graded to relieve subsidence. Tracking in place and BMP.



Pad interim overrun with weeds.



Erosion and rilling on Northern pad perimeter.



Surface roughening appropriate stormwater BMP. Vegetation sparse.