

Shideler 67S92W 20SWNW

Inspection DOC# 675200225

Stormwater around wellheads.



Erosion at retention pond.



Erosion at retention ponds.

