

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/21/2014

Document Number:
669500206

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>215148</u>	<u>311889</u>	<u>ROY, CATHERINE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>501 WESTLAKE PARK BLVD</u>
City:	<u>HOUSTON</u> State: <u>TX</u> Zip: <u>77079</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Campbell, Patti		patricia.campbell@bp.com	All SW Inspections

Compliance Summary:

QtrQtr: SESW Sec: 3 Twp: 33N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/05/2009	200205059	PR	PR	SATISFACTOR Y			No
02/19/2008	200126991	ES	PR	SATISFACTOR Y			No
06/18/2007	200120536	PR	PR	SATISFACTOR Y			No
01/13/2006	200087751	PR	PR	SATISFACTOR Y		Pass	No
01/22/2004	200052440	PR	PR	SATISFACTOR Y		Pass	No
02/05/2003	200036305	PR	PR	SATISFACTOR Y		Pass	No
07/10/2001	200019393	PR	PR	SATISFACTOR Y		Pass	No
02/08/2000	200004332	PR	PR	SATISFACTOR Y		Pass	No
02/04/1998	500148580	PR	PR			Pass	No
01/22/1998	500148579	PR	PR			Pass	No
03/18/1996	500148578	PR	PR				No
07/28/1994	500148577	PR	PR			Pass	No
05/27/1994	500148576		PR				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
215148	WELL	PR	02/26/1985	GW	067-06753	FORD D 1A	PR	<input checked="" type="checkbox"/>
273357	WELL	PR	01/01/2012	GW	067-08963	DODD 33-8-3 4	PR	<input type="checkbox"/>
283803	WELL	PR	03/01/2012	GW	067-09121	DODD 33-8-3 6	PR	<input type="checkbox"/>
284390	WELL	PR	02/01/2012	GW	067-09142	DODD 33-8-3 5	PR	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AV): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	Rig cable in southwest corner of well pad.	Need to remove rig cable.	08/31/2014
STORAGE OF SUPL	ACTION REQUIRED	Roll of fencing by house tap equipment (southwest corner of well pad) and unused chain link fencing stacked around jersey barriers near well head.	Need to remove unused fencing from well pad.	08/31/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Concrete jersey barriers around all equipment.		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Plunger Lift	1	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			

Flow Line	1	SATISFACTORY		
Deadman # & Marked	4	SATISFACTORY	Several markers down on the well pad.	Locate and mark all deadmen.
Ancillary equipment	1	SATISFACTORY	Telemetry	
Bird Protectors	1	SATISFACTORY		
Gas Meter Run	1	SATISFACTORY		
Ancillary equipment		SATISFACTORY	Domestic house tap equipment.	

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL	37.128400,-107.709010

S/A/V: SATISFACTORY	Comment:
---------------------	----------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Tank painted white, berm unpainted and rusting.	Corrective Date
-------------------	---	-----------------

Comment

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 215148

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215148 Type: WELL API Number: 067-06753 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: It does not appear that the interim reclamation area has been seeded. There are a few rabbitbrush (Ericameria nauseosa) growing within the interim reclamation area. However, the area is mostly bare ground. See attached Photo 1.

- 1003a. Debris removed? Fail CM See comments above
 CA Remove rig cable and unused fencing from well pad. CA Date 08/31/2014
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Fail

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? Fail Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland
 Top soil replaced _____ Recontoured _____ 80% Revegetation Fail

Inspector Name: ROY, CATHERINE

1003 f. Weeds Noxious weeds? I

Comment:

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

Comment:

Corrective Action: Date _____

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: **ACTION REQUIRED** Corrective Date: **08/31/2014**

Comment: The top 6 to 8 inches of soil in the southwestern corner of the well pad appears to have been washed downhill toward an irrigation canal below the well pad (See photos 2 and 3). Evidence of stormwater channels (2 to 4 inches deep and 10 to 15 inches wide) washing through this area were observed.

CA: Stormwater exiting the well pad needs to be properly diverted and filtered. The cut and fill slopes surrounding the well pad need to be revegetated and stabilized.

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Site does not meet Reclamation Regulations. Please submit a Form 4 when work has been completed for the location with the following attachments: 1. An invoice and/or documentation showing that all work has been completed on the site that directly relates to the actions required on this inspection. 2. Photographs of the vegetation in four cardinal directions as well as one close up of the plant community. Photographs will also be required documenting stromwater management on the well pad.	RoyC	07/22/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669500227	Photo 1. Southern portion of interim reclamation area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392286
669500228	Photo 2. Stormwater channel eroding southeastern corner of well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392287
669500231	Photo 4. Roll of fencing needs to be removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392288
669500232	Photo 3. Stormwater channel eroding southeastern corner of well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392289