

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/25/2014

Document Number:

673704951

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	235115	317052	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Wreath, Dana	(316) 265-3311X6720	dwreath@berexco.com	
Reynolds, Rodney	(620) 345-9878	reynoldsr@berexco.com	
Richmond, Emma	(316) 337-8370	ecrichmond@berexco.com	

Compliance Summary:QtrQtr: SWSW Sec: 17 Twp: 3N Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/18/2008	200201251	PR	PR	ACTION REQUIRED			Yes
10/24/2007	200121206	PR	PR	SATISFACTOR Y			No
07/19/2005	200075036	PR	PR	SATISFACTOR Y		Pass	Yes
03/17/2004	200051506	PR	PR	SATISFACTOR Y		Pass	Yes
08/27/2001	200019562	PR	PR	ACTION REQUIRED		Fail	Yes
08/27/2001	200020179	PR	PR	ACTION REQUIRED		Fail	Yes
10/03/1995	500158930	PR	PR			Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
105912	PIT		09/23/1999		-	WILLIAMS	<input type="checkbox"/>
105913	PIT		09/23/1999		-	WILLIAMS	<input type="checkbox"/>
117705	PIT		09/23/1999		-	WILLIAMS 2	<input type="checkbox"/>
235115	WELL	PR	07/01/2011	OW	121-07270	WILLIAMS 2	TA <input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 235115

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 235115 Type: WELL API Number: 121-07270 Status: PR Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: May 2014 TA.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Sherman, Susan

Comment:

Corrective Action:

Date:

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:

Date Interim Reclamation Completed:

Land Use:

Comment:

1003a.

Debris removed?

CM

CA

CA Date

Waste Material Onsite?

CM

CA

CA Date

Unused or unneeded equipment onsite?

CM

CA

CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA

CA Date

Guy line anchors removed?

CM

CA

CA Date

Guy line anchors marked?

CM

CA

CA Date

1003b.

Area no longer in use?

Production areas stabilized ?

1003c.

Compacted areas have been cross ripped?

1003d.

Drilling pit closed?

Subsidence over on drill pit?

Cuttings management:

1003e.

Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?

Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced

Recontoured

Perennial forage re-established

Inspector Name: Sherman, Susan

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Inspector Name: Sherman, Susan

Pit Type: Produced Water Lined: NO Pit ID: Lat: 40.222320 Long: -103.114810

Lining:

Liner Type: Liner Condition:

Comment:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Netting:

Netting Type: Netting Condition:

Comment:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard:

Pit (S/A/V): Comment:

Corrective Action: Date:

Pit Type: Skimming/Settling Lined: NO Pit ID: Lat: 40.222420 Long: -103.114690

Lining:

Liner Type: Liner Condition:

Comment:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Netting:

Netting Type: Netting Condition:

Comment:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Pit (S/A/V): Comment: Open excavation between pit and treater house. Three soil stock piles on location. Battery equipment gone. Treater house still in place.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
Form 27 was submitted to COGCC for pit closure and remediation of impacted soil. Operator is in the process of the remediation plan.	ShermaSe	07/28/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673704970	Beren Williams 2 Bat soil stock pile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395649
673704971	Beren Williams 2 Bat W treater house and pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395650
673704972	Beren Williams 2 Bat tank stairs_crop field	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395651
673704973	Beren Williams 2 wellhead TA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395652
673704974	Beren Williams 2 wellhead TA2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395653
673704975	Beren Williams 2 Bat W toward pit stained soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395654

673704976	Beren Williams 2 Bat stained soil near treater house	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395655
673704977	Beren Williams 2 Bat excavation S of Pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395656
673704978	Beren Williams 2 Bat pit n	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395657
673704979	Beren Williams 2 Bat crop field	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395658
673704980	Beren Williams 2 Bat treater shed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395659
673704981	Beren Williams 2 Bat tank pad E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395660