



1.) Location entrance. Culvert and cattle guard intact.



2.) Location BMPS gravel and fencing remain intact.




3.) Pit remains.





4.) Inside Transect conducted.



5.) Inside transect beginning.





6.) Midpoint perpendicular photo 1.



7.) Midpoint perpendicular photo 2