

Federal SP 32-14

Inspection DOC# 675200326

Erosion in SE corner of
fill slope.



Erosion and rilling
behind separators.



Well API # 05-045-19704

Still in XX status.

