

Site Photos (05-001-09529) 7/25/14

Erosion on south side of location



Rill formation along south side of location



Southeast side of location.



Severe cut in bank on North side of location.



Weed growth around perimeter of location.



Weed growth along the soil stockpile.



Soil stockpile.



Tall weed growth on south side of location.



Weed growth on well pad.



Weed growth on well pad.



Weed growth around North side of location.



Ponding occurring on well pad.

