



Photo 1. View of unused Tol-pac, damaged culvert, and debris in northwestern corner of well pad.



Photo 2. View of poor revegetation in interim reclamation area from southeastern corner of project area facing center. Vegetation is largely field bindweed (*Convolvulus arvensis*).



Photo 3. View of interim reclamation area from approximate northeastern corner of well pad facing southward. Run-on from unvegetated interim reclamation area onto well pad can be seen.