



Photo 1. View from northeastern corner of project area toward center.  
Note sufficient grass cover within interim reclamation area.





Photo 2. View from southwestern corner of project area toward center.  
Note sparse cover within interim reclamation area.





Photo 3. View of erosive feature on the western edge of the well pad.