



Photo 1. View of southern portion of interim reclamation area facing eastward with areas that are revegetated sufficiently and areas that are not revegetated sufficiently.



Photo 2. View of northern portion of interim reclamation area facing westward with a small area that is sufficiently revegetated and the majority of the area not sufficiently revegetated.



Photo 3. View of sediment that has discharged off of the interim reclamation area slopes onto the working area in the northeastern corner of the well pad.



Photo 4. View of rill erosion from southern edge of working area onto the interim reclamation area.