



Photo 1. View of unused culvert in northeastern corner of project area.



Photo 2. View of western portion of interim reclamation area facing southward.



Photo 3. View of northern portion of interim reclamation area facing westward.



Photo 4. View of rill erosion along southern edge of well pad.