

South Shale Ridge 1-8H

Inspection# 675200516

Parraffin spill



Parraffin dripping off rods pulled from well.



Fencing material to be removed



No stormwater BMPs in place.
Access to pipeline.



Rods from Pump Jack.



Fencing material to be removed

