

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/13/2014

Document Number:
671000046

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>290186</u>	<u>335841</u>	<u>LUJAN, CARLOS</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10091</u>
Name of Operator:	<u>BERRY PETROLEUM COMPANY LLC</u>
Address:	<u>1999 BROADWAY STE 3700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Johnson, Derek	970-285-2200	dsjohnson@linnenergy.com	District Production Superintendent
Fischer, Alex		alex.fischer@state.co.us	EPS supervisor Western Region
Hughes, Jim		jimo.hughes@state.co.us	EPS SW Region
Spencer, Stan		stan.spencer@state.co.us	EPS NW Region
Hogelin, Thomas		THogelin@linnenergy.com	Construction Foreman
Burns, Bryan	(303) 999-4245	bburns@linnenergy.com	Sr. EHS
Lujan, Carlos		carlos.lujan@state.co.us	EPS NW Region

Compliance Summary:

QtrQtr: NWSE Sec: 20 Twp: 5S Range: 96W

Inspector Comment:

Chevron J-20. Signs in place. No weeds observed onsite (other than on stockpile berms). Tanks labeled and with appropriate secondary containment. Well heads fenced. No junk. No staining observed. Landfarm operation in process (approved Form 04) Pit to be backfilled.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286734	WELL	XX	10/04/2013	LO	045-12771	CHEVRON 20-28D	XX
286735	WELL	XX	10/03/2013	LO	045-12770	CHEVRON 20-21D	XX
286736	WELL	XX	10/03/2013	LO	045-12769	CHEVRON 20-30D-ST	XX
286737	WELL	XX	10/03/2013	LO	045-12768	CHEVRON 20-19D	XX
286738	WELL	XX	10/03/2013	LO	045-12767	CHEVRON 20-18D	XX
286739	WELL	XX	10/03/2013	LO	045-12766	CHEVRON 20-17D	XX
290186	WELL	PR	08/16/2010	GW	045-14045	CHEVRON 20-31D	PR
290187	WELL	XX	10/03/2013	LO	045-14044	CHEVRON 20-32D	XX
423848	PIT	AC	07/28/2011		-	CHEVRON J-20	AC

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 290186

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	423848	1642036	

COGCC Comments		
Comment	User	Date
<p>1) Pit Facility #423848 was permitted as a completion and production pit. It must be closed by Rule via Form 27. Pit closure is in process but no Remediation Work Plan was found on file. Operator may have submitted a Form 27 in the past. If that is the case, please provide a copy of the submittal to enter it in the database. If Form 27 has not been submitted, please do so ASAP, to be in compliance.</p> <p>Note 1: Include analytical results from bottom of the pit with a figure indicating location of sampling.</p> <p>Note 2: Landfarming was approved via Sundry.</p> <p>Note 3: Draft Form 27 submitted on 09/15/2014. Submit Form 27, including statistically representative sampling plan for pit bottom, stockpile (s) and landfarmed material. Describe landfarming operations, including depth of material in cells. Include tentative dates for pit closure, landfarming, etc.</p> <p>- Remove vegetation from berms.</p>	lujanc	08/28/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000052	PhotoReport Linn J-20	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3436722