



Photo 1. View from northeastern corner of well pad toward center. Straw wattle appears to be functioning properly.



Photo 2. View of access road alignment from well pad facing westward.



Photo 3. View of vegetation transect within well pad facing eastward.



Photo 4. Birdseye view of vegetation at midpoint of transect within the well pad area.