

SOUTHWESTERN ENERGY PRODUCTION COMPANY – 10396

API # 107-06263 Inspection Photographs (19 total) 09/08/2014



1. Location as shown on Google Earth, 2011 imagery.



2. Location sign and information at entrance acceptable.



3. Location looking East from main road.



4. Entrance stormwater bmps performing (1).



5. Entrance stormwater bmps performing (2).



6. Entrance cut stable.



7. Northern face cut stable.



8. Cut on opposite side of access road (South) stable.



9. Looking West at North side cut from NE corner.



10. Diversion above North cut tracked with stormwater check-dams.



11. Looking South at East pad perimeter from NE corner.



12. Yellow Toadflax (Class B, Colorado noxious weed) observed along 100' of West pad perimeter, approximately 50 plants in sagebrush within the vicinity.



13. Topsoil stockpile tracking (1). Stockpile wraps around SW to SE of pad.



14. Topsoil stockpile tracking (2). Stockpile wraps around SW to SE of pad.



15. Check dams on Eastern diversion appear minimal for angle of diverted stormwater flow. May breach without increased velocity reduction.



16. Sheep-foot surface roughening on fill areas of location.



17. Waddles on West perimeter yet to be installed.



18. Equipment parking acceptable (1).



19. Remove equipment off of vegetation and back onto location(2) (on West perimeter).