



Photo 1. View of southern edge of well pad facing westward.



Photo 2. View of area that appears to be pipeline disturbance within interim reclamation area that is weedy and not revegetated.



Photo 3. View of silt trap in western portion of interim reclamation area that is filling with sediment.



Photo 4. View of straw wattle and vegetation that appear to be effectively filtering and de-energizing stormwater flows exiting the western edge of the project area.



Photo 5. View of unused straw wattles that need to be properly installed or removed from project area.