



Photo 1. View of western portion of interim reclamation area from the southern edge facing northward.



Photo 2. View from northwestern corner of well pad facing center.



Photo 3. View of rill erosion on eastern edge of well pad.



Photo 4. View of more rill erosion on eastern edge of well pad.