



Photo 1. View of northern edge of project area from northwestern corner facing eastward.



Photo 2. View of southern edge of project area from southeastern corner facing westward.



Photo 3. View of eastern edge of project area from southeastern corner facing northward.



Photo 4. View of rill erosion occurring on the eastern edge of the well pad area.