



Photo 1. View of western edge of project area and adjacent habitat from southwestern corner facing northward.



Photo 2. View of northern edge of project area from southwestern corner facing eastward.



Photo 3. View of cut slope on the eastern edge of the project area. Rill erosion is occurring on the slope and sediment is running onto the well pad.



Photo 4. View of sediment deposition on the well pad at the base of the cut slope shown in Photo 3. Sediment appears to be contained but erosion needs to be monitored.



Photo 5. View of rill erosion on the southwestern corner of the project area.