



Photo 1. View of the western edge of the project area from the northwestern corner facing southward. Good vegetative cover throughout the majority of the interim reclamation area.



Photo 2. View of an area within the eastern portion of the interim reclamation area with poor revegetation that needs to be monitored and possibly re-seeded.





Photo 3. View of southern portion of interim reclamation area with good revegetation.



Photo 4. View of rill erosion on the cut slope within the northern portion of the interim reclamation area.





Photo 5. View of sediment run-on from the western edge of the access road near the entrance to the well pad.