



Photo 1. View of silt trap largely full of sediment within the northern portion of the interim reclamation area.



Photo 2. View of erosional channel downstream from silt trap within the northern portion of the interim reclamation area.



Photo 3. View of unused drip line within western portion of the interim reclamation area.