



Photo 1. Infestation of Scotch thistle within the eastern and northern portion of the interim reclamation area.





Photo 2. Barbed wire near the northeastern edge of the interim reclamation area and the working area of the well pad.



Photo 3. View of eastern portion of the interim reclamation area with good grass cover and slope stabilization.





Photo 4. View of erosional channel eroding the eastern edge of the access road and depositing sediment on the well pad.





Photo 5. View of silt trap in western portion of interim reclamation area containing significant stormwater flows.



Photo 6. View of western portion of interim reclamation area with silt trap full of water and ponding on the well pad that does not appear to be on the driving surface and does not appear to be overflowing off of the well pad.