



Photo 1. View of trash within the northeastern corner of interim reclamation area.



Photo 2. View of unused pipe within the western portion of the interim reclamation area.



Photo 3. View of gully that is approximately 3 to 4 feet wide by 3 to 4 feet deep within eastern portion of the interim reclamation area.



Photo 4. View of Canada thistle population downstream of erosional gully in Photo 3; growing in what appears to be sediment deposited from gully.



Photo 5. View of rill erosion on the fill slopes within the interim reclamation area.



Photo 6. View of water diversion channel directing stormwater flows off of the northern edge of the well pad.



Photo 7. View of head-cut where water from stormwater diversion channel is eroding slope and meets up with access road.



Photo 8. View of erosion along the access road that needs BMPs to de-energize and filter stormwater flows.