



Photo 1. View of southern portion of interim reclamation area from southeastern corner facing westward.



Photo 2. View of northern portion of working area and interim reclamation area from northwestern corner facing eastward.





Photo 3. View of large cobble and straw wattle BMP that appears to be effectively de-energizing and filtering stormwater flows.



Photo 4. View of rill erosion off of the southern edge of the working area.