



Photo 1. View from southwestern corner of project are facing center. Poned area can be seen in background. Poor revegetation in foreground.



Photo 2. View of erosive feature on southern edge of the project area where it appears stormwater overflows ponded area to this drainage.



Photo 3. View of erosion and poor revegetation on cut-slope in western portion of the project area.



Photo 4. View of more erosion and poor revegetation on cut-slope in western portion of the project area.



Photo 5. View of gully forming within the cut-slope in the western portion of the project area.



Photo 6. View of unused culvert in project area.