



Photo 1. View of revegetation along the western portion of the interim reclamation area.



Photo 2. View of partially buried and unmarked guy line anchor as well as partially buried rig cable within the northwestern corner of the project area.



Photo 3. View of gully forming on the southern edge of the well pad near the entrance.



Photo 4. View of rill erosion and sediment run-on along the northern cut-slope for the well pad.