



Photo 1. View from western edge of project area facing eastward over northern portion of project area that needs to be revegetated.



Photo 2. View from eastern edge of project area facing westward over northern portion of project area that needs to be revegetated.





Photo 3. Erosional channel forming along the eastern side of the access road.





Photo 4. View of poor revegetation and rill erosion on slopes within the eastern portion of the project area.





Photo 5. View of grasses becoming established within the western portion of the project area.