



Photo 1. View of dead musk thistle and revegetation within the interim reclamation area.



Photo 2. View of revegetation within the eastern portion of the interim reclamation area from southeastern corner facing northward.



Photo 3. View of dead vegetation within the interim reclamation area on the downslope side of the working area of the well pad.



Photo 3. View of erosional channel forming within the eastern portion of the interim reclamation area that needs to be monitored.