



Photo 1. View of rig cable that needs to be removed in northern portion of well pad next to driving surface.



Photo 2. View of dead vegetation with understory of weeds within teardrop of well pad.



Photo 3. View of dead vegetation within southwestern corner of interim reclamation area.



Photo 4. View of Canada thistle and musk thistle rosettes within interim reclamation area.



Photo 5. View of musk thistle dying back and rosettes of thistles within northern portion of the interim reclamation area.



Photo 6. View of sediment deposition from cut slope on the eastern edge of the project area. Appears to be largely contained by the vegetated diversion adjacent to the access road.



Photo 6. View of large rill within cut slope that needs to be monitored.