

Site Photos (05-099-06868) 10/16/2014

Looking Southwest at location



Pipeline riser remains on East side of the location



Site Photos (05-099-06868) 10/16/2014

Pipeline riser remains on the South side of location




Center of location, wood debris remains




Site Photos (05-099-06868) 10/16/2014

Onsite Transect Northwest



Onsite Transect Ground Cover



Site Photos (05-099-06868) 10/16/2014

Onsite Transect Southwest




Onsite Transect Northeast




Site Photos (05-099-06868) 10/16/2014

Onsite Transect Southeast



Offsite Transect Northeast



Site Photos (05-099-06868) 10/16/2014

Offsite Transect Groundcover



Offsite transect Northwest



Site Photos (05-099-06868) 10/16/2014

Offsite transect Southeast



Offsite transect Southwest



Site Photos (05-099-06868) 10/16/2014

Bare area approx. 30'x30' in center of location



Weed growth on location: Russian thistle

