



Photo 1. View of eastern portion of project area from southeastern corner facing northward.



Photo 2. View of musk thistle rosettes within the interim reclamation area.



Photo 3. View of large Russian thistle plants growing next to the facilities that needs to be removed.



Photo 4. View of erosion from diverted stormwater flows along the northern edge of the project area.



Photo 5. View of rill erosion within the western portion of the interim reclamation area.