



Photo 1. View of Scotch thistle (*Onopordum acanthium*) rosettes within the project area.





Photo 2. View of rill and gully erosion occurring within the western portion of the project area.





Photo 3. View of erosional drainage forming along the eastern edge of the access road near the entrance to the well pad.





Photo 4. View of erosion occurring along the western edge of the project area.





Photo 5. View of rill erosion on one of the cut slopes within the project area.





Photo 6. View of rill erosion and sediment deposition below cut slopes within the project area.