

Gunnison Energy LLC – Federal 16-4 (API 051-06023)

Inspection# 675200785

Access to Federal 16-4 via NFSR
884. Locked gate limits vehicle
traffic.



Access past gate via hiking,
horseback or bike allowed.



Location of heater that caught on fire. Stairs damaged. Debris from burnt tires still visible. (Heater had been removed from location prior to inspection)



Wellhead still covered. New heater attached.



New heater located in front of
workover rig and away from well.




Damage to accumulator
containment. Containment still
functional.



Damaged load indicator.



Hoses damaged by fire, that had been repaired by crew prior to inspection.



Workover rig and area fire occurred. Fire extinguishers in place around area.



Existing equipment on location. No signage on tank. Tank containment and areas around equipment need weeds/vegetation managed.

