

Federal 26-3 API#045-06213 Inspection performed 11/7/2014



Wellhead sign is on the fence at the tank battery.



Fluids around wellhead appear to be from workover operation to repair casing.



Appears to be cement drilled out following casing repair operation.



Separator stack is not equipped with a bird protector.