

Site Photos (05-055-06315) 10/30/2014

West side of location SMU 7-15-I

photo #1



Northwest side of location facing west where timber was cut

photo #2



Site Photos (05-055-06315) 10/30/2014

Facing west where timber was cut

photo #3



Thick wood debris remains impeding plant vegetation growth

photo #4



Site Photos (05-055-06315) 10/30/2014

East side of location looking West

photo #5



East side of location looking West

photo #6



Site Photos (05-041-06072) 9/19/2014

Stumps remain from tree cutting

photo #7



Southeast corner of the location looking Northeast

photo #8



Site Photos (05-055-06315) 10/30/2014

Thick layer of wood debris remains

photo #9



Wood debris 5" thick in areas

photo #10



Site Photos (05-055-06315) 10/30/2014

Wood debris on location

photo #11



Cattle guard to this location is damaged

photo #12

