



Photo 1. View of southeastern portion of project area from southern corner facing north-northeastward.



Photo 2. View of rill erosion adjacent to cobble BMP in northeastern portion of project area.





Photo 3. View of good revegetation and stabilization around culvert inlet.





Photo 4. View of rill erosion along drill seed rows within interim reclamation area.





Photo 5. View of rill erosion where there is little revegetation within the interim reclamation area and stormwater exiting the well pad.





Photo 6. View of rill erosion and thistles around culvert inlet.