



Photo 1. View of revegetation within the southern portion of the project area from the southwestern corner facing westward.



Photo 2. View of diversion drainage (approximately 2 feet wide and 1 foot deep) near well pad entrance that appears to be down-cutting. This drainage should be monitored and BMPs applied if down-cutting/erosion worsens.



Photo 3. View of culvert outlet at well pad entrance that is full of sediment and rocks.



Photo 4. Sediment run-on to the well pad from erosion in the southern portion of the project area. This needs to be monitored and BMPs applied if erosion worsens.