



Photo 1. View of scotch thistle plant in foreground, within the eastern portion of the interim reclamation area.





Photo 2. View of water diversion channel in southeastern portion of project area.





Photo 3. View of rill erosion along cut slope in southern portion of interim reclamation area.